


# NAVISTAR® Fuel Injectors

| DESCRIPTION   | OEM CROSS REFERENCE                                 | BRAND   | NEW       | REMAN   |
|---|---|---|-----------|---------|
| T444E   | 1816187C3, 1818259C2, 1821752C1,                    |  | AP63800AA |         |
|   | 1822803C1, 1823561C1, 1824582C94,                   |   | AP63801AB |         |
|   | 1824474C2, 1822890C1, 1824472C1,                    |   | AP63802AC |         |
|   | 1823751C91, 1823751RX91, 1831487C92, 1831488C1,     |   | AP63803AD |         |
|   | 1833639C1, 1833640C1, 1833644C1,                    |   | AP63804AE |         |
| VT365   | 1843089C95, 1843481C95, 1845879C91,                 |   | AP60800   | AP60900 |
|   | 1844751C2, 1845150C92, 1846692C2, 1877748C1,        |   | AP60801   | AP60901 |
| MaxxForce® 7  | 1873422C93, 4307381R91, 4307369R91, 5010359R93,     |   | AP64800   | AP64900 |
|   | 1883110C1, 1883111C92, 1899239C92, 6904-PP, 6921-PP |   | AP64801   | AP64901 |
| DT466, I530E, DT466/530, HT530                      | 1819834C1, 1823736C94, 1824917C2,                   |   | AP63805BA |         |
|   | 1824739C1, 1824742C91, 1824918C2,                   |   | AP63806BB |         |
|   | 1824740C1, 1824743C91, 1824919C2,                   |   | AP63807BC |         |
|   | 1824741C2, 1824744C94, 1824920C2,                   |   | AP63808BD |         |
|   | 1824839C94, 1829336C1, 1829837C2, 1829838C94,       |   | AP63809BE |         |
|   | 1830145C91, 1830146C94, 1830147C2,                  |   | AP63810BF |         |
|   | 1830559C91, 1830560C2, 1830561C92,                  | AP63811BI   |           |         |
|   | 1830094C92, 1830570C92, 1830571C2, 1830572C93,      | AP63812BJ   |           |         |
|   | 1830691C1, 1830692C91, 1830693C1,                   | AP63813BN   |           |         |
|   | 1836250C1, 1836251C91, 1836252C91, 1836253C1        | AP63814BP   |           |         |
|   | DT466/570, HT570,<br>MaxxForce DT/9/10              | 1848718C93, 5010561R93, 6912-PP, 6929-PP  | AP66818   | AP66918 |
| 1848721C93, 4307212R91, 5010823R91,                 |   | AP66821   | AP66921   |         |
| 1890055C92, 1890056C2, 5010715R91, 6915-PP, 6932-PP |   | AP66855   | AP66955   |         |
| 1884057C92, 1884058C2, 5010986R91, 6914-PP, 6931-PP |   | AP66857   | AP66957   |         |
| 1890057C92, 1890058C2, 5010717R91, 6916-PP, 6933-PP |   | AP66858   | AP66958   |         |
| 1842576C94, 5010656R92, 1841491C91, 1842223C91,     |   | AP66876   | AP66976   |         |
| 1842577C94, 5010657R92, 1842224C91,                 |   | AP66877   | AP66977   |         |
| 1842578C95, 5010658R92, 1842225C91,                 |   | AP66878   | AP66978   |         |
| 1842579C95, 5010659R92, 1842226C91,                 |   | AP66879   | AP66979   |         |
| 1848489C92, 5010983R91, 6909-PP, 6926-PP            |   | AP66889   | AP66989   |         |
| 1848492C92, 5010984R91, 6910-PP, 6927-PP            |   | AP66892   | AP66992   |         |

|             |  |              |               |               |
|-------------|--|--------------|---------------|---------------|
|             | 1848495C92, 5010985R91, 6911-PP, 6928-PP |              | AP66895       | AP66995       |
| MaxxFace 11 | 3005555C91                               | <b>BOSCH</b> | 0 445 120 179 | 0 986 435 566 |
|             | 3005797C92                               |              | 0 445 124 010 | 0 986 435 577 |
| MaxxFace 13 | 3005556C91                               |              | 0 445 120 180 | 0 986 435 567 |
|             | 3005783C92                               |              | 0 445 124 013 | 0 986 435 578 |
|             | 3005556C91                               |              | 0 445 120 180 | 0 986 435 567 |
|             | 3005783C92                               |              | 0 445 124 013 | 0 986 435 578 |